LOUISIANA MACHINERY CO. L.L.C

Custom Track Service

Percent Worn

CATERPILLAR®

Prepared for: Louisiana Cat

Prepared by: Louisiana Cat

Phone Number:

Model:	D6N LGP	Hour Meter Reading:	4,146	Inspection Date:	3/2/2018
Manufacturer:	Caterpillar	Hours Per Week:		Next Inspection Date:	
Serial Number:	PBA1972	Odometer Reading:		Next Inspection Hours:	
Equipment Number:		Forward Odometer Reading:		Last Service Date:	3/2/2018
Undercarriage Code:	C1462	Reverse Odometer Reading:		Underfoot Conditions	
Link Manufacturer:	Caterpillar	Job Site:	Hammond, La	Impact:	Moderate
Roller Manufacturer:	Caterpillar	Track Sag:	Left / Right	Abrasion:	Moderate
Idler Manufacturer:	Caterpillar			Moisture:	Moderate
Hour Meter Works:	Yes	Frame Extension:	2.64 / 2.76	Packing:	Moderate
		Maximum:	4.30	Bushing Allowable Wear:	Greater
		Dry Joints:		Link Allowable Wear:	Greater

Position	Status		Date Installed		SMU Installed		Hours On Wear Surface		Tool Used	Measurement (Inches)		Percent Worn	
	Left	Right	Left	Right	Left	Right	Left	Right		Left	Right	Left	Right
LINKS					Sections:		46	Track Group:		Link Assembly:			
	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Ultrasonic	1.44	1.44	3 %	3 %
BUSHINGS					Bushing - SystemOne								
Internal	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Tape	30.00	30.00	0 %	0 %
External	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Ultrasonic	0.47	0.47	6 %	6 %
SHOES					Master Shoes:			Shoe - Extreme Service		Width:		30.00 (Inches)	
	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Ultrasonic	2.80	2.85	21 %	18 %
IDLERS			Front:			Rear:			Idler - Center Tread				
Front	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Depth Gauge				
Rear	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Depth Gauge				
CARRIER ROLLERS					Carrier Roller - SystemOne								
Front	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Ultrasonic	1.78	1.79	24 %	23 %

TRACK ROLLERS — Single Flange: — Double Flange:

	L	R													
Front	S	S	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Ultrasonic	1.54	1.56	33 %	30 %
2	D	D	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Ultrasonic				
3	S	S	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Ultrasonic	1.61	1.58	22 %	27 %
4	D	D	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Ultrasonic	1.58	1.56	27 %	30 %
5	D	D	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Ultrasonic	1.59	1.58	26 %	27 %
6	S	S	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Ultrasonic	1.59	1.58	26 %	27 %
7	D	D	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Ultrasonic				
8	S	S	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Ultrasonic	1.53	1.51	35 %	38 %
Swapped			---	---	---	---	---	---	---	---	---	---	---	30 %	30 %

SPROCKETS			First:					Second:				
	Original	Original	3/2/2018	3/2/2018	4,146	4,146	0	0	Tape	Good		Good

LINK ROLLER SYSTEM													
Worst	---	---	---	---	---	---	---	---	---	---	---	19 %	21 %
Swapped	---	---	---	---	---	---	---	---	---	---	---	17 %	17 %

NOTES: